



Under the *European Union (Drinking Water) Regulations 2023*, the Environmental Protection Agency (EPA) is the supervisory authority in relation to Uisce Éireann and its role in the provision of public drinking water supplies. This audit was carried out to assess the performance of Uisce Éireann in providing clean and wholesome water to the public water supply named below.

The audit process is a sample of the performance of a water treatment plant and public water supply on a given date.

Water Supply Zone		
Name of Installation	Scarriff PWS	
Organisation	Uisce Éireann	
Scheme Code	0300PUB1006	
County	Clare	
Site Visit Reference No.	SV28373	

Report Detail

Issue Date	14/12/2023
Prepared By	Orla Harrington

Site Visit Detail

Date Of Inspection	23/11/2023	Announced	Yes	
Time In	11:20	Time Out	12:10	
EPA Inspector(s)	Orla Harringt	on		
Additional Visitors				
Company Personnel	Uisce Éirean	Uisce Éireann: Tommy Roche, Liam Honan		
	Clare County	Council (working in par	tnership with Uisce Éireann): Denis Mo	roney



Summary of Key Findings

1. There is no treatment barrier to *Cryptosporidium* entering the water supply from the boreholes serving the Scarriff Public Water Supply. Uisce Éireann were unable to confirm the protozoal log treatment requirement for the supply and no monitoring for *Cryptosporidium* in line with *Uisce Éireann's Rationale for Determining the Frequency of Cryptosporidium in Public Water Supplies* is currently taking place at the water treatment plant.

2. There are no plant shutdowns in place based on chlorine residual levels after chlorine dosing and after contact time has been achieved to prevent inadequately treated water entering the supply.



Scarriff Public Water Supply (PWS) serves a population of approximately 851 people and produces 525 m3 of treated water per day. Raw water is sourced from three boreholes. A fourth borehole located 2km west of the water treatment plant (WTP) is used to augment the supply when necessary and can provide up to 43 m3/day. Treatment of the combined water consists of chlorination. The treated water is then fed to the on-site reservoir.

The audit was undertaken to assess Uisce Éireann's performance in producing clean and wholesome drinking water with a focus on the alarms and inhibits in place at the treatment plant and the procedures in place to ensure appropriate oversight of treatment processes.



The audit included an inspection of the water treatment plant and its critical monitoring equipment and controls. The borehole at the water treatment plant was also inspected as part of the audit.



No

1. Abstraction for the supply is from three boreholes. There is one active borehole at the WTP referred to as the 'new borehole' which was visited during the audit. This borehole is located below ground level in a concrete chamber with a lockable manhole lid. On the day of the audit, some ingress of surface water on the base of the chamber was evident.

2. The other two boreholes are located 7 km from the WTP and operate in a duty/standby arrangement, producing approximately 290 m3/day. These were not visited during the audit. Clare County Council advised that security is poor at these boreholes.

3. A fourth borehole is located 2km from the plant and is used to augment the supply, when required.

Has the protozoal com	pliance log treatment requirement been identified for the	No
water treatment plant?		
Comment		

2. At present, there is no monitoring being carried out in accordance with the Uisce Éireann Rationale for Monitoring Cryptosporidium in Public Water Supplies.

3. There is no treatment barrier to *Cryptosporidium* entering the water supply from the boreholes serving the supply.



3. Alarms, Inhibits & Oversight Audits 2023

	Answer	
Did staff confirm they have received training on the site specific incident response and incident escalation process?	No	
Comment		

		Answer
.2	Is continuous monitoring located appropriately to verify treatment performance?	No
	Comment	
	1. A review of data from the residual chlorine monitor after dosing (CL001) showed	•

21/11/2023 and 23/11/2023. Clare County Council stated that inconsistent flow through CL001 is causing the spikes in the trend data and that they are not responding to alarms from that monitor.

	Answer	
Are dial out arrangements suitable to allow a timely response?	No	
Comment		
1. There is no alarm cascade system in place on this supply. The caretaker is the only person who is currently notified of the dial out alarms.		

Were all findings of the UÉ alarm and inhibit review implemented?	No
Comment	

		Answer
8.5	Are suitable plant shutdowns/inhibits in place to prevent the entry of inadequately treated water entering the distribution network?	No
	Comment	

1. There are no shutdowns based on low or high chlorine in the final water.

2. At the time of the audit, there was a 2000 second (33.3 minutes) system delay for the chlorine alarms. The EPA's Water Treatment Manual: Disinfection recommends a maximum of 5 minutes delay on chlorine alarms.

	Answer	
Are plant performance trends accessible by operational staff at the water treatment plant?	No	
Comment		
1. The residual chlorine trend was visible on the plant HMI and indicated stable it has limited functionality as the HMI screens are small, difficult to navigate and trends for more than 7 days at any one time. A dedicated SCADA terminal at the would allow operational staff increased ease of access to plant process information performance data.	d it is not possible to view the treatment plant	

Answer

3.7	Are plant performance trends accessible remotely? No		
	Comment		
	1. Uisce Éireann advised that they do not have remote access to performance trend data from the plant.		

	Answer	
s there appropriate oversight of plant performance trends?	No	
Comment		

1. On the day of the audit, there was no information available on how plant performance trend data is reviewed by supervisory staff.

	Answer	
Is there appropriate oversight of alarm responses?	No	
Comment		
1. There is no cascade system in place. The caretaker is the only person getting alarms.		

		Answer
3.10	Is there a documented alarm response procedure?	No
	Comment	
	1. On the day of the audit, it was not confirmed if there was a documented alarm procedure in place.	

		Answer	
3.11	Did staff confirm they have been trained on the alarm response procedure?	No	
	Comment		
	1. On the day of the audit, it was not confirmed if staff had been trained on the alarm response procedure.		

		Answer	
12	Are there appropriate procedures covering verification of alarms and inhibits status following maintenance or other work on site?	No	
	Comment		
	1. It could not be confirmed at the audit if there are procedures covering verification of alarms following maintenance or other work on site.		

Subject	Scarr	iff PWS - Audit Report	Due Date	15/01/2024
Action Text		e Éireann is responsible for ensuring a clea should implement the following recommen		
	1.	a) Confirm the protozoal log treatment requi treatment deficit will be addressed and c) mo <i>Éireann Rationale for Monitoring Cryptospor</i>	onitor the supply in	accordance with the Uisce
	2.	Disinfection: a) Ensure the residual chlorine and working appropriately. This monitor sho device to ensure that a failure of the chlorine Install automatic shutdown based on low and ensure adequate disinfection in line with EP	uld be alärmed and e dosing system is i d high levels for ch	I linked to a recording immediately detected; b) lorine in the final water to
	3.	Implement the findings of the Alarm and Inhit treated water quality.	ibit review to protec	ct treatment processes and
	4.	Ensure that a) a formal site specific alarm re plant. The procedure should clearly docume delegation of responsibilities for operational staff on the requirements of the alarm respo	nt the corrective ac and relief staff; b) p	ctions and set out
	5.	Ensure that a) the treatment plant is connect process information and trended performance supervisory staff via SCADA and c) that the water treatment plant performance data which trends by operational and supervisory staff.	ce data are availab re are robust syster	le to operational and ms of review and checks on
	6.	Ensure there is a procedure in place for care that all alarms have been correctly re-set on		
	7.	Source Protection: a) ensure all raw water s chambers are adequately sealed and mainta have regard to EPA Advice Note No.14: Bor when carrying out these works.	ained to prevent su	rface water ingress and c)
	8.	Put in place an appropriate cascade system plant.	for responding to a	alarms generated at the
	Actio	ons required by Uisce Éireann		
	During the audit, Uisce Éireann representatives were advised of the audit findings and that ac must be taken by Uisce Éireann to address the issues raised. Uisce Éireann should submit a report to the EPA on or before 15/01/2023 detailing the actions taken and planned, with timescales, to close out the above recommendations.			
		EPA advises that the findings and recommend ant, be addressed at other public water supplied		dit report should, where