

Site Visit Report

Under the *European Union (Drinking Water) Regulations 2023*, the Environmental Protection Agency (EPA) is the supervisory authority in relation to Uisce Éireann and its role in the provision of public drinking water supplies. This audit was carried out to assess the performance of Uisce Éireann in providing clean and wholesome water to the public water supply named below.

The audit process is a sample of the performance of a water treatment plant and public water supply on a given date.

Water Supply Zone		
Name of Installation	Crookhaven	
Organisation	Uisce Éireann	
Scheme Code	0500PUB4501	
County	Cork	
Site Visit Reference No.	SV33127	

Report Detail	
Issue Date	20/10/2025
Prepared By	Joanne Creedon

Site Visit Detail				
Date Of Inspection	22/09/2025	Announced	Yes	
Time In	13:35	Time Out	13:59	
EPA Inspector(s)	Joanne Cree	Joanne Creedon		
Additional Visitors				
Company Personnel		Uisce Éireann: Brian Harrington, Claire Hurley. Cork County Council (working in partnership with Uisce Éireann): Barry O' Meara.		

>

Summary of Key Findings

The Crookhaven water treatment plant (WTP) produces approximately 116 m3/d of water serving a population of 112. This audit is an inspection of the Crookhaven WTP and is focused on the disinfection system.

>

Introduction

Disinfection consists of chlorination. The audit found that the disinfection system was operating satisfactorily on the day of the audit.



Supply Zones Areas Inspected

This audit assessed the chlorination disinfection system at Crookhaven WTP.

1. Disinfection Audits 2025

		Answer
		.,
	Is chlorination used for primary disinfection?	Yes
		Answer
		Allower
	Did Uisce Éireann confirm the type of chlorine disinfectant in use?	Yes
		Answer
	Are there duty and standby chlorine dosing pumps in place?	Yes
		Answer
- 1	Is there automatic switchover in the event of failure of one of the chlorine dosing pumps?	Yes
		I
		Answer
	Is the chlorine dosing rate flow proportional?	Yes
		Answer
	Is there a continuous residual chlorine monitor, with alarm, to verify chlorine dosing is taking place at the target level?	Yes
		Answer
	Is there a continuous residual chlorine monitor, with alarm, at a suitable sample location after contact time has been completed?	Yes
		Answer
	Can data trends from the online residual monitor be viewed on site?	Yes
		Answer
		Allawei
	Are there low and high chlorine alarm settings on each chlorine monitor?	Yes
		_
		Answer
	Is there a documented alarm response procedure for responding to chlorine alarms?	Yes

	Answer
Have staff been trained on the chlorine alarm response procedure?	Yes
Г	
	Answer
Are chlorine alarms dialled out via a cascade system to allow a timely response by plant operators?	Yes
	Answer
Is there automatic shutdown of the supply in the event of the chlorine level dropping below the low level or rising above the high chlorine alarm setting?	Yes
The spirit of the second secon	
	Answer
Are service due / monitoring instrument calibration dates for the chlorine monitors within date?	Yes
	Answer
Is the site specific target contact time being achieved?	Yes
Is the site specific target contact time being achieved?	Yes
Is the site specific target contact time being achieved?	Yes Answer
Is the site specific target contact time being achieved? Is the residual chlorine level ≥ 0.1 mg/l at the extremity of the distribution network?	
Is the residual chlorine level ≥ 0.1 mg/l at the extremity of the distribution	Answer
Is the residual chlorine level ≥ 0.1 mg/l at the extremity of the distribution	Answer

Recommendations

Subject	Crookhaven - Disinfection Audit	Due Date	19/11/2025		
Action Text	Uisce Éireann is responsible for ensuring a clean and wholesome supply of drinking water and should implement the following recommendation without delay.				
	Ensure that the disinfection stage continues to be suitably managed and operated at all times.				
	Actions required by Uisce Éireann				
	During the audit, Uisce Éireann representatives were advised of the audit findings and that action must be taken by Uisce Éireann to address the issues raised.				
	udit report should, where				