

Site Visit Report

Under the *European Union (Drinking Water) Regulations 2023*, the Environmental Protection Agency (EPA) is the supervisory authority in relation to Uisce Éireann and its role in the provision of public drinking water supplies. This audit was carried out to assess the performance of Uisce Éireann in providing clean and wholesome water to the public water supply named below.

The audit process is a sample of the performance of a water treatment plant and public water supply on a given date.

Water Supply Zone			
Name of Installation	Adrigole		
Organisation	Uisce Éireann		
Scheme Code	0500PUB4201		
County	Cork		
Site Visit Reference No.	SV31975		

Report Detail	
Issue Date	18/06/2025
Prepared By	Paul Buckley

Site Visit Detail						
Date Of Inspection	21/05/2025	Announced	Yes			
Time In	11:00	Time Out	12:30			
EPA Inspector(s)		Paul Buckley Regina Campbell				
Additional Visitors						
Company Personnel	Uisce Éireann - Brian Harrington, Sharon O'Dwyer, Claire Hurley. Cork County Council (working in partnership with Uisce Éireann) - Con O'Sullivan, Michael Russell.					

>

Summary of Key Findings

- 1. The water treatment plant is well operated and managed on a day to day basis.
- 2. The protozoal log treatment requirement for the source of the Adrigole Public Water Supply has not been determined. The source and sanitary survey has been completed and was in the peer review process at the time of the audit.



Introduction

The Adrigole Public Water Supply (PWS) supplies an average of 326 m3/day, serving a population of 233 people.

The supply is sourced from the Clashduff River, with the intake located adjacent to the plant. Treatment consists of pH correction, pressure filtration, ultraviolet (UV) disinfection and chlorination. This is not refelctive of the treatment types listed on the EPA EDEN system.

The audit was undertaken to assess Uisce Éireann's performance in producing clean and wholesome water with a focus on the protozoal barriers in place at the water treatment plant.



Supply Zones Areas Inspected

The intake, pH correction system, pressure filtration system, ultraviolet disinfection system, and the chlorination system were inspected.



1. Protozoal Barriers Audits 2025

		Answer
1.1	Has UÉ identified the protozoal compliance log treatment requirement for the water treatment plant?	No
	Comment	

The protozoal compliance log treatment requirement has not been determined. The source and sanitary survey has been completed and is in the peer review process.

Recommendations

Subject	EPA Audit Recommendations Adrigole 21052025	Due Date	18/07/2025			
Action Text	 Uisce Éireann is responsible for ensuring a clean and wholesome supply of drinking water and should implement the following recommendation(s) without delay. 1. i) Confirm the protozoal log treatment requirement for the Adrigole supply and ii) confirm how any log deficit, if identified, will be addressed. 2. Update EDEN with the correct treatment types in place at the plant. 					
	During the audit, Uisce Éireann representatives were advised of the audit findings and that action must be taken by Uisce Éireann to address the issues raised.					
	Uisce Éireann should submit a report to the EPA on or before 18/07/2025 detailing the actions taken and planned, with timescales, to close out the above recommendations.					
	The EPA advises that the findings and recommendations from this audit report should, where relevant, be addressed at other public water supplies.					