BAT 28 Response

Heavy metal limits will be complied with and periodically monitored at Kiln 6.

Effective dust removal techniques are proposed at Kiln 6, refer to BAT 17 which outlines measures to reduce dust emissions from flue-gases of kiln firing processes.

No combustion takes place of raw materials or fuels at the Coal Mill. Therefore the BAT limit does not apply.

For inspection purposes only.
Consent of copyright owner required for any other use.

EPA Export 16-02-2017:02:18:52