


SITE VISIT REPORT


Purpose of Site Vis	it: Peat Extraction in Co. Tipperary
Site Address:	Monaincha, Thesheehys and Corville townlands, Roscrea, Co Tipperary
Date of Visit:	14/02/2025
Times of Visit:	10:35am to 11:45am
Visit Criteria:	Peat extraction investigation
EPA Attendees:	Mick Henry and Kealan Reynolds
 i) Ascertain wheth Monaincha, These Monaincha, These Monaincha, These Monaincha, These Monaincha, These Was in photography. • The site was in photography. • There was no perfect that the northern part of the northern part of the morthern part of the site (and the northern part of the site (but the northern part of the site (continued for extract the northern part of th	as noted to be building a new access road coming from the existing ne south of the site and running across the part of the site previously ing milled peat (Photo 3). It that are used for large sod peat extraction were noted to be parked ern and western side parts of the site.
Report prepared by:	Kealan Reynolds Signed: Keclas Ray of M. Skanns
	1 Car Francis

Date:

19/03/2025










Photo 1: Photograph showing area of recently excavated large sod peat at the northern part of the peatland.



Photo 2: Area to the south of the peat land with significant amount of large sod peat excavated.



Photo 3: New road being constructed across the peatland.



Photo 4: Excavator parked on northern part of the site.



Photo 5: Excavator with large sod peat attachment parked on northern part of the site.